
Forming and finishing the Embankments



Blocks stacked in the quarry in the bottom of the reservoir looking East 16th June 1909.

Grizedale Lea, North embankment looking North East 6th June 1914

Central in the embankment is the puddle clay core. Formed of soft clay, this was 'puddled' into place in thin layers by the workmen wearing high heeled boots to ensure a continuous barrier was formed.



Drawing showing section of embankment - between Feb 27th 1907 and 30th Sept 1921.



